

CDR Thomas J. Thompson, DSN 757-9115

NAMP Administration & Management

- In an ongoing effort to improve the Navy's organizational, operational, and communications alignment, a substantial reorganization concerning naval aviation maintenance policy has occurred.
- Implementation, administration, and management responsibility for the Naval Aviation Maintenance Program (NAMP) is now delegated to Commander Naval Air Forces (N422).
- OPNAV retains NAMP policy oversight



The NAMP

Establishes and standardizes
policy and procedures and assigns
responsibilities for the conduct of
aviation maintenance at all three
levels -

O-, I-, & D-



The NAMP Is

The NAMP is collaborative

E/VE/R

- ANYONE in the fleet can submit corrections, recommend changes, and request deviations.
- The <u>cooperative effort</u> among the fleet, the TYCOMS, COMNAVAIRFOR, FMF, and COMNAVAIRSYSCOM (AIR-6.9.2.2) -- constantly enhances aviation maintenance processes, procedures, and maintenance practices to benefit Fleet Sailors and Marines.

<u>DYNAM</u>

CREVISIONSDEVIATIONS

- Constant & continuous review and regular updates through the NAMP process:
 - CHANGES

NAMP <u>Policy</u> Committee meets as required

- Chair COMNAVAIRFOR (N422)
- OPNAV, Fleet Readiness Division (N433)
- OPNAV, Air Warfare Division, Aviation Maintenance Programs Branch (N781)
- Fleet Forces Command (N433)
- Commander Naval Air Systems Command
 - AIR-6.0 Logistics
 - AIR-6.0 Depot
- Commandant of the Marine Corps
- Chief of Naval Air Training
- Commander, Naval Air Reserve Force
- Commander, Naval Supply Systems Command

NAMP <u>WORKING</u> Committee meets semi-annually

- CNAF N422C (or designee) Chair
- OPNAV, Fleet Readiness Division (N433)
- OPNAV, Air Warfare Division, Aviation Maintenance Programs Branch (N781)
- Commander, Fleet Forces Command (N433)
- Commander, Naval Air Systems Command
 - AIR-5.0, AIR-6.0 Logistics, AIR-6.0 Depot
- Commandant of the Marine Corps
- Chief of Naval Air Training
- Commander, Naval Air Reserve Force
- Commander, Naval Supply Systems Command

NAVAIR NAMP Team (AIR-6.9.2.2 (3.3.3))

CDR Tom Thompson Division Head DSN 757-9115

Mr.Ken Musil NAMP Project Team Lead DSN 757-9114 A Z C S A I L in thic um N A M P T e a m L C P O A c tin g D S N 7 5 7 - 9 1 4 0

Mr.Ken Drake
Change Coordinator
Corrections
DSN 757-9117

Mrs. Linda Embach Electronic NAMP Manager Technical Editor DSN 757-9159 ATCS Dave Hertzog
CSEC Analyst
Change Coordinator
DSN 757-8840

Mr. Dan Middleton CSEC Programmer DSN 757-9120 AZCS AlLinthicum
Change Coordinator
Forms/Reports
DSN 757-9140

AMCS Dave Hendricks on Change Coordinator Publications/Directives DSN 757-9138

GySgtEd DalsingChange Coordinator
CHARTS / NOMMP / NAMDRP
DSN 757-9141

ADC Patrick Flores
Change Coordinator
Deviations
DSN 725-7346

AEC Bob SteadyChange Coordinator
DSN 757-9145

ATC Steve Upshaw
Change Coordinator
CHARTS Administrator / Acronyms
DSN 757-9137

AZ1 Clifton Bullock
Change Coordinator
Definitions
DSN 757-9113




NAVAIR NAMP Team Services

- NAMP Coordinator
 - ✓ Develop and submit changes to COMNAVAIRFOR for approval
 - **✓** Coordinate and incorporate corrections
 - **✓** Process requests for deviations
- NAMP distribution
 - **✓Online (primary)**
 - **✓ CD-ROM (only as required)**
- CHARTS
- CSEC

Note: for NAMP policy interpretation contact cognizant

NAMP Change Procedures

- Modifies existing NAMP policies and procedures.
- Anyone can submit a NAMP change recommendation.
- Submit by naval letter via chain of command to TYCOM: Ref COMNAVAIRFOR 4790.2 Vol. I pg 1-3
 - TYCOM submits change to NAVAIR (AIR-6.9.2.2) via CHARTS.



NAMP CHANGE STATUS

- Since 4790.2H implementation 2 July 2

```
Submitted:
```

111

Approved:

53

Working Committee Review:

4

Impact/Coordinator Review:

6



Pending CNO Approval/Disapproval

NAMP Correction Procedures

- Modifies administrative discrepancies:
 - punctuation, grammar, capitalization, spelling, syntax, tense, typographical errors, word omissions.
- Does not affect policies or procedures.
- Submit by naval letter directly to:
 - COMNAVAIRSYSCOM (AIR-6.9.2.2)

NAMP Deviation Procedures

- Departure from NAMP policies, procedures and responsibilities.
- Granted by COMNAVAIRFOR for specific duration, situation, or circumstance.
 - Revoked upon NAMP revision.
 - Not posted online and do not have fleet-wide application.
- Submit by naval letter via chain of command to COMNAVAIRFOR (N422) with copy to NAVAIR (AIR-6.9.2.2).
 - TYCOM has approval authority on deviations based on mannower

Online Resources

	A I			-34				
				- The same		Search		
LOGISTICS (N	AVAIR 3.0) - I	Providing W	orld Class Supp	ort To The Wa	urfighter		:: CONTACT US	
About Us	Products	Library	Logistics Tools	Initiatives	Support	Training	Links	Site Index
		The Nav	/al Aviatic	n Mainte	enance P	rogram	(NAMP)	

General Links

Homepage

Site Links

- CNO's Implementation Message
- OPNAVINST 4790.23
- COMNAVAIRFORINST 4790.2
 - Volume I
 - Volume II
 - Volume III
 - Volume IV
 - Volume V
- NAMP Download
- Comments
- CSEC

Homepage

In support of the Chief of Naval Operation's (CNO's) guidance to improve the Navy's organizational and communications alignment, the Office of the Chief of Naval Operations (OPNAV) has delegated responsibility for administrative and management functions related to the Naval Aviation Maintenance Program (NAMP) to Commander, Naval Air Forces (COMNAVAIRFOR). OPNAV shall retain policy oversight and program sponsorship per the OPNAVINST 4790.2J Basic Instruction.

COMNAVAIRFORINST 4790.2 is the initial version of the NAMP implemented under the cognizance of COMNAVAIRFOR. This instruction is an extensive revision which supercedes OPNAVINST 4790.2H. It issues the maintenance policies, procedures, and responsibilities for the conduct of the NAMP at all levels of maintenance throughout naval aviation.

A self-extracting file is available for <u>download</u>. The contents of this file shall be extracted to replace existing OPNAVINST 4790.2H files on computers and servers. After extracting namp.zip, open NAMP folder and access the NAMP instruction by opening the contents.pdf file. Recommend creating a shortcut to contents.pdf.

NAMP Change Recommendations, Corrections, and Requests for Deviation must be submitted per COMNAVAIRFORINST 4790.2, Chapter 1, paragraph 1.4, of each volume.

Comments pertaining to the NAMP are welcome.

http://logistics.navair.navy.mil/479

```
RAAUZYUW RUEWMCS0332 1050005-UUUU--RUHOCNU.
ZNR UUUUU
R 150005Z APR 05
FM PTC EMAIL SYSTEM WASH DC
INFO RUHOCNU/CNO EMAIL CUSTOMER//CNOONIPRDA//
R 150005Z APR 05 ZYB
FM CNO WASHINGTON DC//N781//...
BT
UNCLAS //N04790//
MSGID/GENADMIN/CNO WASHINGTON DC/N781/APR//
SUBJ/REALIGNMENT OF THE NAVAL AVIATION MAINTENANCE PROGRAM (NAMP)//
REF/A/DOC/OPNAVINST 4790.2J/01FEB2005//
REF/B/DOC/COMNAVAIRFORINST 4790.2/01FEB2005//
REF/C/DOC/OPNAVINST 4790.2H/01JUN2001//
NARR/REF A IS OPNAVINST 4790.2J, THE NAMP POLICY AND OVERSIGHT
GUIDANCE INSTRUCTION. REF B IS COMNAVAIRFORINST 4790.2. THE NEWLY
IMPLEMENTED NAMP. REF C IS OPNAVINST 4790.2H. THE SUPERCEDED NAMP//
POC/SCOTT RETTIE/CDR/OPNAV/LOC:N781C3/TEL:COMM 703-604-7704/
DSN 664-7704/EMAIL SCOTT.RETTIE(AT)NAVY.MIL//
POC/THOMAS THOMPSON/CDR/OPNAV/LOC:AIR 6.9/TEL:COMM:301-757-9115/
DSN 757-9115/EMAIL THOMAS.J.THOMPSON1(AT)NAVY.MIL//
POC/TOMMY SUMMERS/CDR/CNAF/LOC:N422C/TEL:COMM:619-545-1323/
DSN 735-1323/EMAIL TOMMY.SUMMERS(AT)NAVY.MIL//
```

RMKS/1. THIS MESSAGE IMPLEMENTS A SUBSTANTIAL REORGANIZATION IN AVIATION MAINTENANCE POLICY AS PART OF OUR ONGOING EFFORT TO IMPROVE THE NAVY'S ORGANIZATIONAL. OPERATIONAL. AND COMMUNICATIONS ALIGNMENT. RESPONSIBILITY IS NOW DELEGATED TO COMMANDER, NAVAL AIR FORCES (COMNAVAIRFOR) FOR IMPLEMENTATION, ADMINISTRATION, AND MANAGEMENT OF THE NAVAL AVIATION MAINTENANCE PROGRAM (NAMP), AND COMNAVAIRFOR SHALL BE THE PRIMARY AUTHORITY FOR ASSIGNMENT OF MAINTENANCE RESPONSIBILITIES AND TASKS. OPNAV SHALL RETAIN POLICY OVERSIGHT AND PROGRAM SPONSORSHIP, AS OUTLINED IN REFERENCE (A). 2. REFERENCE (B) IS THE NAMP AS IMPLEMENTED BY COMNAVAIRFOR. THIS IS AN EXTENSIVE REVISION THAT SUPERCEDES REFERENCE (C) AND SHALL BE COMPLETELY REVIEWED. ALL SUBORDINATE DIRECTIVES AND INSTRUCTIONS IN CONFLICT WITH THE PROVISIONS OF EITHER THE OPNAV OR COMNAVAIRFOR INSTRUCTION SHALL BE REVISED TO ENSURE CONFORMITY. NEW POLICIES AND PROCEDURES SHALL ENSURE AN INTEGRATED APPROACH THAT INVOLVES APPROPRIATE STAKEHOLDERS AND ADDRESSES ASSUMPTIONS, RISKS, IMPACTS, AND OPTIMAL USE OF RESOURCES RELATED TO MATERIAL CONDITION. MAINTENANCE/MANUFACTURE/CALIBRATION PRACTICES, MANPOWER, RESOURCE PROGRAMMING, AND BUDGETING. ADDITIONALLY, NAVAL AVIATION MAINTENANCE POLICY SHALL CONTINUE TO PROVIDE FOR THE COLLECTION. ANALYSIS, AND USE OF PERTINENT DATA TO ACHIEVE COST-WISE AVIATION READINESS.

- 3. PREVIOUS NAMP DEVIATIONS APPROVED BY OPNAV WITHOUT A TERMINATION DATE ARE CANCELLED. ACTIVITIES SHALL REVIEW THEIR CURRENT APPROVED DEVIATIONS AND REQUIREMENTS AND RESUBMIT TO COMNAVAIRFOR IF STILL REQUIRED. A GRACE PERIOD OF 30 DAYS FROM THE DTG OF THIS MESSAGE IS IN EFFECT TO ALLOW FOR RESUBMISSION OF REQUESTS, WHICH SHALL BE SUBMITTED PER REFERENCE (A).
- 4. PAPER COPIES AND CD-ROM VERSIONS WILL NOT BE DISTRIBUTED. THE NAMP WILL CONTINUE TO BE ACCESSED ONLY VIA THE WEB AT HTTP://LOGISTICS.NAVAIR.NAVY.MIL/4796/. A SELF-EXTRACTING FILE (NAMP.ZIP) WILL BE AVAILABLE FOR DOWNLOAD FROM THE NAMP DOWNLOAD HYPERLINK BY 18 APR 05 AND MUST BE EXTRACTED TO REPLACE EXISTING OPNAVINST 4790.2H FILES ON ALL COMPUTERS AND SERVERS THAT MAINTAIN A CURRENT VERSION OF THE NAMP NLT 01 MAY 05. USERS SHOULD ACCESS AS FOLLOWS: AFTER EXTRACTING NAMP.ZIP, OPEN NAMP FOLDER AND ACCESS THE NAMP INSTRUCTION BY OPENING THE CONTENTS.PDF FILE. RECOMMEND CREATING A SHORTCUT TO CONTENTS.PDF. USERS WHO ENCOUNTER DOWNLOAD OR WEB CONNECTIVITY PROBLEMS SHOULD CONTACT COGNIZANT WING/TYCOM/ACC OR NAVAIR POC: CDR THOMAS THOMPSON, LISTED ABOVE.

- 5. THE LATEST COMPUTERIZED SELF EVALUATION CHECKLIST (CSEC 5.0) IS
 AVAILABLE FOR FLEET USE CONCURRENT WITH THE RELEASE OF
 COMNAVAIRFORINST 4790.2. THE PREVIOUS CSEC DATABASES SHALL BE
 RETAINED FOR A MINIMUM OF ONE YEAR FOR FILING PURPOSES. USER
 GUIDANCE, INSTALLATION INSTRUCTIONS AND PROGRAM DOWNLOAD LINKS ARE
 AVAILABLE AT HTTP://LOGISTICS.NAVAIR.NAVY.MIL/CSEC. THE CURRENT CSEC
 VERSIONS (502K AND 5097) CANNOT BE MERGED WITH THE PREVIOUS VERSIONS
 (402K AND 4097) AND MUST BE OPERATED SEPARATELY. USERS WHO
 ENCOUNTER CSEC SOFTWARE RELATED ISSUES SHOULD UTILIZE THE WEBSITE
 REQUEST FOR SUPPORT FORM OR CONTACT NAVAIR POC: ATCS DAVID HERTZOG,
 (301) 757-8840 OR DSN 757-8840.
- 6. DISSEMINATE TO ALL NAMP USER ACTIVITIES./
 BT//

Change History and Review Tracking System (CHARTS)

- Automates the NAMP change process
- Eliminates paper correspondence
- Web based application
- Permits online:
 - Review
 - Comment
 - Mediation
- Working Committee membership vote
- COMNAVAIRFOR (N422)

CHARTS Website Authorized users only; password protected.


	You are logged in as Thomas Thompson (You have CHARTS ADMIN Super Powers). CHARTS Working Change Request							
	CHARTS ADMIN EDIT ADD FILE ATTACHMENT							
CHARTS	PROCESS CHANGE REQUEST							
CHARTO	STATUS:	IN PROCESS - PENDIN	G WORKING COMMITTEE REVIEW					
	CHANGE NUMBER:	2H0411						
CHANGE REQUESTS	NAMP LCPO							
My Pending	MESSAGE							
<u>Submit New Change</u> <u>Request</u>	LETTER	STATUS		ACTION				
<u>In Process</u>	ACKNOWLEDGEMENT	SENT - 1/26/2005 3:08:25 PM		SEND LETTER				
<u>Approved</u>	PMA	NOT REQUIRED		EDIT PMA SETTINGS				
<u>Disapproved</u>	IMPACT	SENT - 1/26/2005 3:08:42 PM		SEND IMPACT LETTER				
<u>Cancelled</u>				RESET IMPACT RESPONSES				
All	W/C Notification	SENT - 3/21/2005 2:54:38 PM		SEND W/C NOTIFICATION RESET W/C VOTES				
SITE TOOLS	OPNAV	NOT SENT		SEND OPNAV NOTIFICATION (WC VOTING NO				
<u>Contacts</u>				COMPLETE) RESET OPNAV VOTE (MUST send OPNAV				
Search Create Feedback				Notification before RESET)				
View Feedback	CHANGE: 2H0411		STATU	S: IN PROCESS				
Change Password	GIAROLI ZIIOTTI			- PENDING WORKING COMMITTEE REVIEW				
Report Matrix	Title:	Соог		linator:				
Report Sortable	Painting of Aircraft and	Support Equipment	Patrick Flores (Send email) (Open contact)					
	Originator:		Coordinator's Remarks:					
APP MGMT	Bill Bennett, AIRPAC							
Manage Team Messages	(Send email) (Open contact) Created On: 01/04/2005	01:59 PM						
USER MGMT	Originator's Recommen	dation:	NAMP Change Documents:					
<u>Create User</u>			Title: Vol II CH 8 (SHOW)					
<u>Edit Users</u>	Title: Original Recommendation (SHOW) Title: Vol I CH 10 (SHOW)							

CSEC

- CSEC provides checklists for work center and program audits mandated by the NAMP.
- NAVAIR (AIR-6.9.2.2) maintains and updates CSEC software and core question database.
 - TYCOM supplemental questions.
 - Type Wing supplemental questions.

NAVAIR (AIR-6.9.2.2) CSEC SUPPORT OFFICE TELEPHONE: (DSN) 757-8840 (C) 301-757-8840

Online Resources



http://logistics.navair.navy.mil/cse

Questions?